

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

ORIGINAL

FIELD NOTES

OF

THE DEPENDENT RESURVEY OF

A PORTION OF THE SOUTH BOUNDARY,

A PORTION OF THE SUBDIVISIONAL LINES,

AND

THE SUBDIVISIONS OF SECTIONS 26, 27, AND 35,

IN

TOWNSHIP 19 SOUTH, RANGE 2 WEST,

OF THE SALT LAKE MERIDIAN  
IN THE STATE OF UTAH

EXECUTED BY

**Ronald K. Batty**  
**Cadastral Surveyor**

Under Special Instructions dated **September 4, 2013**, approved **September 4, 2013**, which provided for the surveys included under Group Number **1221**, and Assignment Instructions dated **September 4, 2013**.

Survey Commenced, **September 13, 2013**  
Survey Completed, **February 14, 2014**

# INDEX DIAGRAM

TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

6	5	4	3	2	1
7	8	9	10	11	12
18	17	16	15	14	13
19	20	21	22	23	8 24
			11	11	8
30	29	28	27	10 26	6 25
				9	6
31	32	33	34	9 35	5 36
			5	4	

The Subdivision of Section 26.....	12
The Subdivision of Section 27.....	14
The Subdivision of Section 35.....	15

## TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

The following field notes are those of the dependent resurvey of a portion of the south boundary, a portion of the subdivisional lines, and the subdivisions of sections 26, 27, and 35, in T. 19 S., R. 2 W., Salt Lake Meridian, Utah.

## HISTORY OF SURVEYS

Surveyed by		Retr. or Resurveyed by	
SOUTH BOUNDARY			
Portion	F. Dickert	1871	
Portion	H. Fitzhugh	1882	H. Fitzhugh (Independent) 1882
Portion	H.D. Heist & E.V. Wooley	1906	H.D. Heist & E.V. Wooley 1906
Portion			F.R. Chappell 1970
Remonumentation			F.D. Reynolds 1972
EAST BOUNDARY			
Portion	S.M. Richardson	1883	
All	H.D. Heist & E.V. Wooley	1906	
Portion			A.R. Talamantes 1909
Portion			C.P. Sylvester 1980
WEST BOUNDARY			
All	S.M. Richardson	1884	
Portion			H.D. Heist & E.V. Wooley 1906
NORTH BOUNDARY			
Portion	F. Dickert	1871	
All	S.M. Richardson	1883	S.M. Richardson 1883
All			H.D. Heist & E.V. Wooley 1906
Remonumentation			F.D. Reynolds 1972
Portion			C.P. Sylvester 1980
Portion			D.G. Gillins 2008-09
SUBDIVISION			
Portion	F. Dickert	1871	
Portion	H.D. Heist & E.V. Wooley	1906	H.D. Heist & E.V. Wooley 1906
Remonumentation			F.D. Reynolds 1972
Portion			C.P. Sylvester 1980
Portion			J.D. Davis 2011

## PRIVATE SURVEYS

A survey was executed by Kary B. Monroe, L.S. 6295, of Jones and Demille Engineering, with survey plat dated November 13, 1989, on file at the Millard County Recorder's Office.

A survey was executed by The Willford Group, with survey plat dated August 2000, on file at the Millard County Recorder's Office.

A survey was executed by Dale J. Robinson, L.S. 189369, of Sunrise Engineering Inc., with survey plat dated October 24, 2003, on file at the Millard County Recorder's Office.

## TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

**PRIVATE SURVEYS CONTINUED**

A survey was executed by Dale J. Robinson, L.S. 189369, of Sunrise Engineering Inc., with survey plat dated June 21, 2004, on file at the Millard County Recorder's Office.

A survey was executed by James D. Edwards, L.S. 162522, of Edwards Surveying, with survey plat dated June 20, 2007, on file at the Millard County Recorder's Office.

## TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

The survey was executed in accordance with the specifications set forth in the Manual of Surveying Instructions, 2009, and the Special Instructions for Group No. 1221, dated September 4, 2013.

The direction of each line is with reference to the true meridian, determined by Global Positioning System (GPS) utilizing Real-Time Kinematic (RTK) techniques throughout the survey. The positional accuracy of this survey complies with the *Standards for the Positional Accuracy of Cadastral Surveys when using Global Navigation Satellite Systems (GNSS)*, dated February 23, 2009. Trimble model R8 GPS receivers were used for field collection. Cadastral Automated Plat Drafting (CAPD) software was the primary software utilized for project calculations.

Preliminary to the resurvey, the lines of the prior surveys were retraced and a search was made for all corners and other calls of record. Identified corners were remonumented in their original positions. Lost corners were reestablished and remonumented at proportionate positions based on the official record. The retracement data was thoroughly verified and only the true line field notes are given herein.

Geodetic control was derived from GPS static observations, post processed by National Geodetic Survey, Online Positioning User Service (OPUS), utilizing Continuously Operating Reference Stations (CORS); KENNECOTT1UT2005 CORS ARP, CORBON COUNTY COU CORS ARP, DELTAMUNI\_UT2004 CORS ARP.

The geographic position of the 1/4 of sections 35 and 36, T. 19 S., R. 2 W., as determined by direct RTK methods from the geodetic control, is as follows:

Latitude: **39°07'06.358" N.**,  
Longitude: **112°02'04.429" W.**, N.A.D. 83 (2011), EPOCH: 2010.00,  
Network Accuracy = 0.200 meter at 95% confidence.

The geographic position of the 1/4 of sections 22 and 27, T. 19 S, R. 2 W., as determined by direct RTK methods from the geodetic control, is as follows:

Latitude: **39°08'23.976" N.**,  
Longitude: **112°03'45.538" W.**, N.A.D. 83 (2011), EPOCH: 2010.00,  
Network Accuracy = 0.200 meter at 95% confidence.

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

---

Dependent Resurvey of a portion of the South Boundary,  
T. 19 S., R. 2 W., Salt Lake Meridian, Utah

---

Reestablishment of the Survey Executed by F. Dickert in 1871, and  
Resurvey Executed by H. Fitzhugh in 1882.

---

Note: The exterior lines of section 34 and 35 were originally surveyed in 1871, by F. Dickert, with meander corners monumented around Scipio Lake. A resurvey of the south boundary of section 34 and 35 was executed in 1882, by H. Fitzhugh. During this survey, the 1871 meander corners were not recovered, the lake had receded, and the west meander corner was remonumented at the 1871 record distance. The east meander corner was monumented at an additional 9 chains west of the 1871 record distance. In 2004, a completion survey of sections 34 and 35 was executed by Dale J. Robinson, L.S. No. 189369, of Sunrise Engineering Inc., survey plat entitled "Boundary Survey, Marden Stone, in section 34 & 35, T19S, R2W, SLM," on file at the Millard County Recorder's Office. The 2004 completion survey was executed by methods not in accordance with the 2009 Survey Manual of Instructions. Meander corners were not recovered or re-monumented during this same survey and the survey plat does not show or reference the meander corners around Scipio Lake.

It was determined that it was in the best interest of all parties involved to accept the 2004 completion survey as is, rather than correct the completion of sections 34 and 35. During the course of this resurvey, the meander corners within sections 34 and 35 were searched for, none were recovered. The meander corners were not remonumented / proportioned.

---

Beginning at the 1/4 section corner of sections 2 and 35, monumented with an aluminum drive stem, 3/4 inch diameter, projecting 18 inches above the ground with a 3 inch diameter aluminum cap marked T19S R2W 1/4 35 2 2006 LS162522. There is no remaining evidence of the original corner and mound of stone. This corner is accepted as the best available evidence of the original corner position.

The corner is located in a fence, extending east and west.

**N. 89°28.7' W.,** between sections 2 and 35.

- 11.500 Point for the 1871 meander corner, at record distance. Not monumented.
- 20.500 Point for the 1882 meander corner, at record distance. Not monumented.
- 40.341 Point for the corner of sections 2, 3, 34, and 35, at proportionate distance. This corner is located in the middle of

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

Scipio Lake where it is impracticable to set a permanent monument. Not monumented. This corner was called for, but not monumented the 1882 resurvey.

N. 89°28.7' W., between sections 3 and 34.

25.450 Point for the 1882 meander corner, at record distance. Not monumented.

40.341 True point for the 1/4 section corner of sections 3 and 34, at proportionate distance, which falls in the middle of a county dirt road. Not monumented.

From which, an aluminum drive stem, 1 inch diameter, firmly set, projecting 8 inches above the ground, as a reference monument, bears S. 86°56.5' W., 42.5 links distance, with a 3 inch diameter aluminum cap, marked T19SR2W 1/4 34 3 28.3 2006 LS162522 with an arrow pointing to the true point.

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 19 S., R. 2 W., Salt Lake Meridian, Utah

Reestablishment of the Survey Executed by F. Dickert in 1871,  
and Resurvey and Survey Executed by H.D. Heist  
and E.V. Wooley in 1906

From the 1/4 section corner of sections 35 and 36, monumented with a bronze disk, 3 inches diameter, firmly set in a concrete base, 6x6 inches, flush with the ground, marked MILLARD COUNTY SURVEY 1/4 S35 S36 T19S R2W RESTORED 1985. There is no remaining evidence of the original corner. This corner is accepted as the best available evidence of the original corner position.

The corner is located in a fence line that extends south-southeasterly and northerly.

N. 0°16.6' W., between sections 35 and 36.

19.933 Point for the N 1/16 section corner of sections 35 and 36.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 25 inches in the ground, with the aluminum cap marked

N 1/16  
S35 | S36  
2013

Set a steel fence post alongside of the aluminum post.

The corner is located in a small hollow draining northerly in dense sagebrush.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

**39.866** The corner of sections 25, 26, 35, and 36, determined at record bearing and distance from the remaining 1906 northwest bearing tree. There is no remaining evidence of the original corner.

From which

A pinion stump, 6 inches high, 19 inches diameter, bears N. 17°30' W., 1.82 chains distance. The tree had been recently cut down and was lying alongside the stump, with visible scribe marks. The tree was removed from the site.

At corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 28 inches in the ground, with the aluminum cap marked

T19S R2W	
S26	S25
S35	S36
2013	

Set a steel fence post on the north side of the aluminum post.

The corner is located on the eastern edge of a road bearing northerly and southerly.

From which, an aluminum drive stem, 3/4 inch diameter, firmly set, bears N. 46°19.8' E., 21.3 links distance, with a 3 inch diameter aluminum cap marked T19SR2W 26 25 35 36 2006 LS162522. Not utilized during the course of this survey.

From the 1/4 section corner of sections 25 and 36, monumented with a limestone, 18x12x6 inches, firmly set, projecting 10 inches above the ground, marked 1/4 on the north face, with a mound of stone, 2 1/2 feet base, 1 foot high to the north of the corner.

At corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 24 inches in the ground, with the aluminum cap marked

T19S R2W	
S25	
1/4	_____
S36	
2013	

Invert and deposit the marked stone alongside the aluminum post.

The corner is located on a southeasterly facing slope.

**S. 89°57.9' W.**, between sections 25 and 36.

**39.872** The corner of sections 25, 26, 35, and 36.



DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

N. 0°23.5' E., between sections 25 and 26.

- 40.334** The 1/4 section corner of sections 25 and 26, monumented with a limestone, 17x9x7 inches, projecting 10 inches above the ground, firmly set, marked 1/4 on the west face; with a mound of stone, 3 feet base, 1 foot high, west of the corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 27 inches in the ground, with the aluminum cap marked

T19S R2W  
1/4  
S26 | S25  
2013

Deposit the marked stone alongside the base of the aluminum post.

The corner is located on the west slope of a small rise, near the top. All trees have been recently cut down, by fuels reduction project.

N. 0°11.1' E., beginning new measurement.

- 39.896** The corner of sections 23, 24, 25, and 26, monumented with a sandstone, 19x11x10 inches, firmly set, projecting 9 inches above the ground, with 2 notches on the south and 1 notch on the east.

From which the 1906 bearing trees

A pinion, 10 inches diameter, bears N. 68° E., 28.5 links distance, blazed and clearly marked. (Record: 27 links)

A pinion, 11 inches diameter, bears S. 59° E., 58 links distance, blazed and clearly marked.

A pinion, 12 inches diameter, bears S. 35° W., 25 links distance, blazed and clearly marked.

A pinion, 16 inches diameter, bears N. 79° W., 20 links distance, blazed and clearly marked.

At corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 24 inches in the ground, in a mound of stone, 2 1/2 feet base, 1 foot high, with the aluminum cap marked

T19S R2W  
S23 | S24  
S26 | S25  
2013

Deposit the marked stone alongside the aluminum post at the base of the mound.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

The corner is located on a ridge descending southeasterly.

From the 1/4 section corner of sections 24 and 25, determined at record distances from the 1906 bearing trees. There is no remaining evidence of the original corner. From which the 1906 bearing trees

A cedar, mostly dead and standing, 12 inches diameter, bears S.  $13^{\circ}38''$  E., 26 links, marked 1/4 S25 BT. (Record: S.  $46^{\circ}$  E.)

A cedar, 24 inches diameter, bears N.  $44^{\circ}28.5''$  W., 53 links marked 1/4 S24 BT. (Record: N.  $30^{\circ}$  W.)

At corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 24 inches in the ground, in a mound of stone, 2 1/2 feet base, 6 inches high, with the aluminum cap marked

T19S R2W  
S24  
1/4 —————  
S25  
2013

The corner is located on a very steep southwest facing rock slide in pinion and juniper growth.

N.  $89^{\circ}48.0'$  W., between sections 24 and 25.

**39.935** The corner of sections 23, 24, 25, and 26.

N.  $0^{\circ}22.5'$  W., between sections 23 and 24.

**39.856** The 1/4 section corner of sections 23 and 24, determined at record distances from the 1906 bearing trees. The original stone was found loose and above ground nearby at the base of a rock slide, clearly out of place and disturbed. From which the 1906 bearing trees

A dead pinion, 5 inches diameter, bears S.  $63^{\circ}$  E., 6 links distance, marked 1/4 S24 BT on an open blaze.

A juniper, 10 inches diameter, bears west, 4 links distance, marked 1/4 S23 BT on an open blaze.

At corner point

Set a magnet, 3/4 inch diameter, 1 inch long, below the surface of a sandstone boulder in epoxy bond. Over which I set an aluminum post, 30 inches long, 2 1/2 inches diameter, in a mound of stone, 5 feet base, 30 inches high, with the aluminum cap marked

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

T19S R2W  
1/4  
S23 | S24  
2014

The corner is located on the westerly bank of a wash draining southerly, surrounded by pinion and juniper growth.

From the point for the corner of sections 2, 3, 34, and 35, on the south boundary of the township, hereinbefore described.

**N. 5°37.2' W.**, between sections 34 and 35.

- 40.315** Point for the 1/4 section corner of sections 34 and 35, at midpoint between section corners. The corner falls in the middle of Scipio Lake where it is impracticable to set a permanent monument. Not monumented. This corner was not monumented during the 1871 survey and the 1906 resurvey.
- 55.630** Point for the 1871 meander corner, at record distance from the corner of sections 26, 27, 34, and 35. Not monumented.
- 80.630** The corner of sections 26, 27, 34, and 35, monumented with an aluminum pipe, 2 1/2 inches diameter, firmly set, projecting 8 inches above the ground, with the aluminum cap marked MILLARD COUNTY LS6295 T19S R2W S27 S26 S34 S35 1989 SURVEY MARKER. There is no remaining evidence of the original corner or mound of stone. This corner is accepted as the best available evidence of the original corner position.

The centerline of U.S. route 50 is approximately 1.5 chains west of the aluminum post.

From the corner of sections 25, 26, 35, and 36.

**N. 89°17.4' W.**, between sections 26 and 35.

- 40.039** The 1/4 section corner of sections 26 and 35, monumented with a sandstone, 17x7x7 inches, projecting 10 inches above the ground, marked 1/4 on the north face, with a scattered mound of stone to the west; with a steel fence post set alongside the corner.

At corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 24 inches in the ground, in a collar of stone, 2 feet base, with the aluminum cap marked

T19S R2W  
S26  
1/4 ———  
S35  
2013

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

Deposit the marked stone alongside the base of the aluminum post.

---

N. 89°25.8' W., beginning new measurement.

20.080 Point for the W 1/16 section corner of sections 26 and 35.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 28 inches in the ground, with the aluminum cap marked

S26  
W1/16 —————  
S35  
2013

The corner is located on a grassy flat, surrounded by dense sage brush.

40.160 The corner of sections 26, 27, 34, and 35.

---

N. 0°02.6' E., between sections 26 and 27.

20.066 Point for the S 1/16 section corner of sections 26 and 27.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 28 inches in the ground, with the aluminum cap marked

S 1/16  
S27 | S26  
2013

Set a steel fence post on the north side of the aluminum post.

The corner is located on flat grassy area surrounded by scattered sage brush.

40.132 The 1/4 section corner of sections 26 and 27, monumented with a sandstone, 23x12x3 inches, firmly set, projecting 10 inches above the ground, marked 1/4 on west face, in scattered mound of stone; with a steel fence post set alongside the east edge of the corner. There is no remaining evidence of the southeast bearing tree.

At corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 24 inches in the ground, in a small collar of stone, with the aluminum cap marked

T19S R2W  
1/4  
S27 | S26  
2013

Deposit the marked stone alongside the base of the aluminum post.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

A two track road is approximately 1.5 chains west of the aluminum post.

---

N. 0°04.4' W., beginning new measurement.

- 38.835 The corner of sections 22, 23, 26, and 27, monumented with a sandstone, 13x8x7 inches, firmly set, projecting 5 inches above the ground, with 2 notches on the south and east edges; with a steel fence post to the southwest of the corner.

All bearing trees are down and dead.

At corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 24 inches in the ground, with the aluminum cap marked

T19S R2W	
S22	S23
S27	S26
2013	

Deposit the marked stone alongside the base of the aluminum post.

The corner is located on the north edge of a small draw, draining westerly.

---

From the corner of sections 23, 24, 25, and 26.

S. 89°44.4' W., between sections 23 and 26.

- 40.302 Point for the 1/4 section corner of sections 23 and 26, at proportionate distance. There is no remaining evidence of the original corner, and bearing trees.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 17 inches in the ground to solid rock, in a mound of stone, 3 feet base, 13 inches high, with the aluminum cap marked

T19S R2W	
S23	
1/4	_____
S26	
2013	

The corner is located on a southeasterly facing slope in thick pinion and juniper growth.

- 80.604 The corner of sections 22, 23, 26, and 27.

---

S. 88°59.6' W., between sections 22 and 27.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

## CHAINS

20.177 Point for the E 1/16 section corner of sections 22 and 27.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 27 inches in the ground, with the aluminum cap marked

S22  
E 1/16 —————  
S27  
2013

A fence extending north and south is 1 link east of the aluminum post.

40.354 The 1/4 section corner of sections 22 and 27, monumented with a fragmented and decayed sandstone, 10x7x5 inches, loosely set in an embedded mound of stone, 4 feet base.

At corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 24 inches in the ground, in a mound of stone, 2 1/2 feet base, 6 inches high, with the aluminum cap marked

T19S R2W  
S22  
1/4 —————  
S27  
2013

Deposit fragments of the stone alongside the aluminum post.

The corner is located in a fence line extending north and south.

From which, an aluminum drive stem, 1 inch in diameter, bears N. 1°10.9' E., 1.52 chains distance, with a 3 inch diameter aluminum cap marked T19S R2W S22 S27 2006 LS 162522, with a nail in a washer on top of an old fence post stump set alongside, and at the intersection of fences, extending east, south, and west.

Note: This aluminum drive stem was not utilized in this survey because the recovered fragmented stone in the embedded mound of stone along an ancient north - south fence is the best available evidence of the 1906 resurvey. The other supporting evidence is a topographic call to Round Valley Creek, which bears, S. 89°43' E., 14.93 chains distance (1906 record bearing and distance).

---

The Subdivision of Section 26,  
T. 19 S., R. 2 W., Salt Lake Meridian, Utah

---

From the 1/4 section corner of sections 26 and 35.

N. 0°05.7' E., on the N-S centerline of section 26.

20.093 Point for the center S 1/16 section corner of section 26. Not

THE SUBDIVISION OF SECTION 26,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

## CHAINS

monumented.

- 40.186** Point for the center 1/4 section corner of section 26, at the intersection with the E-W centerline.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 27 inches in the ground, with the aluminum cap marked

T19S R2W  
C 1/4  
S26  
2013

The corner is located on rolling terrain, gently sloping westerly. A wash, 45 links deep, 75 links wide, draining southwesterly, is approximately 64 links to the northwest of the aluminum post. The corner is surrounded by sage brush and on the edge of pinion and juniper growth.

- 79.551** The 1/4 section corner of sections 23 and 26.

From the 1/4 section corner of sections 25 and 26.

**N. 89°30.3' W.**, on the E-W centerline of section 26.

- 40.243** The center 1/4 section corner of section 26.

- 60.339** Point for the center W 1/16 section corner of section 26. Not monumented.

- 80.435** The 1/4 section corner of sections 26 and 27.

From the W 1/16 section corner of sections 26 and 35.

**N. 0°04.1' E.**, on the N-S centerline of the SW 1/4 of section 26.

- 20.080** Point for the SW 1/16 section corner of section 26, at the intersection of the E-W centerline of the SW 1/4 of section 26.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 25 inches in the ground, with the aluminum cap marked

SW 1/16  
S26  
2013

The corner is located on a gentle west facing slope in thick sage brush and scattered pinion and juniper growth.

- 40.160** The point for the center W 1/16 section corner of section 26.

From the point for the center S 1/16 section corner of section 26.

THE SUBDIVISION OF SECTION 26,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

N. 89°28.0' W., on the E-W centerline of the SW 1/4 of section 26.

20.088 The SW 1/16 section corner of section 26.

40.176 The S 1/6 section corner of sections 26 and 27.

The Subdivision of Section 27,  
T. 19 S., R. 2 W., Salt Lake Meridian, Utah

From the 1/4 section corner of section 27 and 34, monumented with an aluminum pipe, 2 inches diameter, firmly set, projecting 6 inches above the ground, with the aluminum cap marked LS-6295 T19S S27 1/4 R2W S34 1989. There is no remaining evidence of the original corner and the mound of stone. This corner is accepted as the best available evidence of the original corner position.

The corner is located at the intersection of fences extending north, south, east, and west.

N. 0°16.5' W., on the N-S centerline of section 27.

40.223 Point for the center 1/4 section corner of section 27, at the intersection of the E-W centerline.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 25 inches in the ground, with the aluminum cap marked

T19S R2W  
C1/4 S27  
2013

The corner is located at the intersection of fences, extending west and south bears northeasterly, 30 links distance.

78.682 The 1/4 section corner of sections 22 and 27.

From the 1/4 section corner of sections 26 and 27.

S. 89°31.5' W., on the E-W centerline of section 27.

20.110 Point for the center E 1/16 section corner of section 27.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 20 inches in the ground to sandstone bedrock, in a mound of stone, 2 1/2 feet base, 10 inches high, with the aluminum cap marked

E 1/16  
C ——— C  
S27  
2013



THE SUBDIVISION OF SECTION 27,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

## CHAINS

The corner is located on the southwesterly slope of a rocky hill in heavy pinion and juniper growth.

**40.220** The center 1/4 section corner of section 27.

**79.822** The 1/4 section corner of sections 27 and 28, monumented with an aluminum pipe, 2 1/2 inches diameter, firmly set, projecting 10 inches above the ground, with the aluminum cap marked T19S R2W 1/4 S28 S27 1993. There is no remaining evidence of the original corner and the mound of stone. This corner is accepted as the best available evidence of the original corner position.

The corner is located at the intersection of fences, extending south and east. The corner is also on the south edge of a gate.

From the center E 1/16 section corner of section 27.

**N. 0°10.4' W.**, on the N-S centerline of the NE 1/4 of section 27.

**38.647** The E 1/16 section corner of sections 22 and 27.

The Subdivision of Section 35,  
T. 19 S., R. 2 W., Salt Lake Meridian, Utah

From the 1/4 section corner of sections 2 and 35, on the south boundary of the township, hereinbefore described.

**N. 5°44.7' W.**, on the N-S centerline of section 35.

**40.355** Point for the center 1/4 section corner of section 35, at the intersection of the E-W centerline.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 27 inches in the ground, with the aluminum cap marked

T19S R2W  
C 1/4  
S35  
2013

The corner is located in a grassy area, gently sloping westerly, and surrounded by scattered sage brush.

**60.485** Point for the center N 1/16 section corner of section 35.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, with magnet at base, 26 inches in the ground, with the aluminum cap marked

C  
N 1/16 | S35  
C  
2013

THE SUBDIVISION OF SECTION 35,  
TOWNSHIP 19 SOUTH, RANGE 2 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

The corner is located on a gentle, westerly facing slope in heavy pinion and juniper growth.

**80.615** The 1/4 section corner of sections 26 and 35.

---

From the 1/4 section corner of sections 35 and 36.

**N. 89°31.2' W.**, on the E-W centerline of section 35.

**36.204** The center 1/4 section corner of section 35.

**76.450** The point for the 1/4 section corner of sections 34 and 35.

---

From the N 1/16 section corner of sections 35 and 36.

**N. 89°24.0' W.**, on the E-W centerline of the NE 1/4 of section 35.

**38.121** The center N 1/16 section corner of section 35.

---

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**FIELD ASSISTANTS**

Name	Capacity
Christopher J. May	Survey Technician
Matthew N. Gillins	Survey Technician
Jacob Murdoch	Survey Technician

## CERTIFICATE OF SURVEY

I, **Ronald K. Batty, Cadastral Surveyor**, HEREBY CERTIFY upon honor, that in pursuance of Special Instructions bearing the date of the **September 4, 2013**, I have **dependently resurveyed a portion of the south boundary, a portion of the subdivisional lines, and subdivided sections 26, 27, and 35, in Township 19 South, Range 2 West**, of the **Salt Lake Meridian**, in the State of **Utah**, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said Special Instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

Sept 28, 2015  
Date

[Signature]  
Cadastral Surveyor

## CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT  
Salt Lake City, Utah

The foregoing field notes of the **dependent resurvey of a portion of the south boundary, a portion of the subdivisional lines, and the subdivision of sections 26, 27, and 35, in Township 19 South, Range 2 West, Salt Lake Meridian, Utah**, executed by **Ronald K. Batty, Cadastral Surveyor**, having been critically examined and found correct, are hereby approved.

September 30, 2015  
Date

Daniel W. Webb  
Chief Cadastral Surveyor for Utah